




Rompimento de Barragem em Brumadinho/MG - Brasil

Chamado Charter 686

Imagem do Evento - 2019.01.26 - 19:20 - CSA/RADARSAT-2
Imagem pré-evento - 2018.11.25 - CSA/RADARSAT-2
Imagem base - 2018.10.23 - INPE/CBERS4



Legenda

- Lama / Rejeito
- Edificações
- Rios
- Estradas
- Pontes
- Ferrovias



1.000
Metros



Fonte dos Dados

Evento:
CSA / RADARSAT-2
Instrumento: SAR_RAD_2
Obtida em 2019.01.26
Modo: Ultrafine, U71 - Polarization HH

Pré-Evento:
CSA / RADARSAT-2
Instrumento: SAR_RAD_2
Obtida em 2018.11.25
Modo: Multi-Look Fine, MF21 - Polarization HH

Imagem Base:
INPE / CBERS-4
Instrument: panMUX - Resolution 10m
Acquired on 2018.10.23

Feições no terreno:
OpenStreetMap

Disclaimer: Product generated by CENAD (National Center of Risk and Disaster Management – Brazil), through the agreement International Charter “Space and Major Disasters”, Call ID 686, with images provided by CSA / RADARSAT-2 and INPE / CBERS-4. RADARSAT-2 Data and Products © MDA Geospatial Services Inc.(2019) - All Rights Reserved. RADARSAT is an official trademark of the Canadian Space Agency. Land Features: © OpenStreetMap contributors. This product was generated using digital techniques and requires field verification. There is no precision mapping in this product.